

Riverbay Corp. Coop City, N.Y.

The Challenge: The powerhouse had several areas where the asbestos block insulation had become exposed. There were also areas where the cloth wrap covering the asbestos insulation was also in disrepair.



The Solution: Riverbay Corp. chose the FiberTechF-50 Primer and F-51 Sealer Coat for all of the Pipe wrap repairs. The ECI Siliconized Alkyd Primer and Finish Coat were used on direct to metal areas where the temperature ranged between 300 and 400 degrees.

