

Ocean County Municipal Authority, NJ

The Challenge: The client had a failing coating system on each of their silos and wanted to replace it. The surface below the coating system was a bitumen membrane over concrete. They wanted to waterproof the cylindrical surface, which needed to be walkable for routine maintenance.



The Solution: The FiberTech waterproofing membrane system was chosen due to its long term effectiveness, ease of installation, and cost effectiveness. One coat of the F-50 Penetrating Stabilizer primer followed by one coat of the F-51 Sealer Coat was applied to each of the silos.

